



GASTEC's Oxygen detector can quickly and accurately measure oxygen concentrations at a variety of different work sites subject to host of complicated and varying factors.

\*The GOA-7H-S comes with a 5 m sensor cord.

- Small, compact and lightweight, only 110g
- One-touch calibration to oxygen levels of 20.9%
- Explosion proof
- Low power consumption

\*The products may not be sold depending on countries and regions.

## Specifications

Measurement range	0.0 - 25.0 % (enhanced range: 25.1 - 42.0 %)
Measurement principle	Galvanic cell
Sampling method	Diffusion
Indicating accuracy	+/- 0.5%(O <sub>2</sub> )
Alarm threshold	<18%
Display	Digital LCD
Explosion proof	Certified by Japan Ministry of Health, Labour and Welfare (Class Ex ia IIC T3 Ga / Certification No.TC22573)
Operating Temperature / Humidity range	Temperature : -10 - 40 °C Relative humidity : 30 - 90 %RH
Power source	One AAA alkaline battery provides about 4000 hours of operation (when no alarm signal is emitted)
Dimensions	48(W) x 37(D) x 105(H) mm
Weight	110g